

Chief Ship Surveyor

Received from Chief Ship Surveyor

NAME *Steel S.S. "SCYTHIA"*Rpt. *Am*
*hw*No. *1892*
82618

arks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

"The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report (24/5/02.)

verse No. *110.5*Depth "d" *23.75*ng: Table No. *-*Description *Bull-angle frame & stressed frame*tudinal No. *66355**And as approved*Proportions Length = *9.76*
Depth =Sheerstrake *as approved*

Vessel has been examined in dry dock at Liverpool and the Survey for official purposes completed with the exception that two Stone-Lloyd W.T. doors in No. 121 require to be put in good working order and tested.

This vessel appears to have been built in accordance with the plans and the approved plans, and it is submitted she is eligible to be classified subject to two Stone-Lloyd W.T. doors in Bulkhead No. 121 being put in good working order & tested and classed *100-A-1. (Steel) Shelter Deck* with freeboard, as recommended. The Summer freeboard of *15.3* from centre of disc of statutory deck line at *II* deck, now marked on the vessel's sides, to be inserted in the classification certificate, and recorded in the Register Book, and further, the remaining freeboards, shown on the accompanying verification form to be inserted in the certificate of classification.

(Steel) & Shelter Dk (Steel pt w/s) & Shade Dk (Steel w/s) 3rd Dk (Steel) in forward & after holds
3522' 2559t, ITF 47' 1630t, Tanks at Sides of tunnels 48' 3/4t, FRT 127t, APT 706
2 BK to Shelter Dk, pt Cam, Hatches A & C, 628t in Shade Dk
to of build 12.20
18.21 hw

It is concluded no tanks are arranged for the carriage of oil fuel or cargo only, but that the requirements of Section 49 of the Rules have been complied with, but the Surveyors should state if this is so.