

Class is subject to

the after intermediate shaft coupling fracture being examined and dealt with as necessary before the end of March 1960.

4E

111 JUL 1960

Received by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

SHIP'S NAME

SANTIAGO

REPORT

VPO.

No. 4335

SRL :- The above item examined and considered to remain efficient and the Surveyor recommends that the coupling be re-examined and dealt with as necessary before the end of July 1960

It is submitted that this vessel is eligible to remain as CLASSED.

Subject as above with amended date.



© 2020

Lloyd's Register  
Foundation

005387-005396-0268