

5c.12.25.

F.E.

Ship Surveyor

Received from Chief Ship Surveyor

NAME STE & BADJESTAN

Rpt.

Sld

No. 29691

s of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

agreement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also
 finding out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points
 entered in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

rse No.

12442

Depth "d"

27.29

Table No.

✓

Description Channel frames as approved

dinal No.

33673

Proportions

Length

12.5

Depth =

Deck Sheerstrake

as approved

Revised Rule

this vessel appears to have been built in accordance with the
 and the approved plans, and it is submitted she is eligible to
 ed


✱ 100 A.I. (Steel).

1 D* (Stl).

Cell D.B. 340' 12145, D.T.a 28' 11845, F.P.T. 3215, A.P.T. 2665

F.K. 8 B.H. Cem, Lloyd's A CP.

P 35', B 108', F 35'.

Lloyd's Register
Foundation

005480-005488-0045

breadth and thickness at
 margin plate.....

34 at top 40

Spacing

alternate