

S. S. "A K U N A".

Extract from Melbourne Survey Report No. 4051, dated 17.12.26.

FREEBOARD:-

The freeboard assigned in Secretary's letter M. 7.4.26, now examined, cut in and painted. All side scuttles which came within 6" of the load water line have now been permanently closed with riveted (spigot) plates. (Six on port side and five on starboard side).

*This submitted freeboard
certificates be now issued.*

*N.S.
3.2.27*



© 2021

Lloyd's Register
Foundation

005635-005643-0068

Fresh Water Line

above centre of Disc

Indian Summer Line