

"ANDROMEDE II" I

IT IS SUBMITTED the Marseilles  
Surveyor be informed in answer to his letter of  
14. 1. 47.

- (1) That the Owners be strongly advised to re-  
place the damaged engine completely by new  
or approved second hand engine.
- (2) In the event of the suggested repairs to the  
existing engine being decided upon, the repair  
at the outset can only be considered as an  
emergency repair which will require to be kept  
under observation by frequent examinations until  
it is proved reliable.
- (3) It is suggested that until the welding has proved  
itself, strongbacks should be fitted over the  
cylinder tops where considered necessary.  
*or mild steel reinforcements.*
- (4) The strongbacks be removed and the condition  
against the class reviewed in accordance with  
the results of examinations.

W.J.F.

Reh.

21. 1. 47.



© 2021

Lloyd's Register  
Foundation

006467-006478-0213