

1

Sent to Chief Surveyors 16. 10 18

Received from Chief Surveyors

VESSEL'S NAME *Sheelss "West. Laleta"*Report *S. 70*

No. 2823

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

When due

The Anchors have been tested by the Surveyors to the American Bureau & the chain cables at Cardiff & Chester & the New York Committee have assigned the notation of C.P.

Intermediate bulkhead in fore hold (instead of in fore after holds) dispensed with. (letter from Owners received) Stand pumps have been dispensed with as a war emergency measure at Owners request.

100 A. 1. (Steel)

2 Dks (Steel)

Cell DTB 356" 11046. FRT. 108L. ART. 4416.

EK. Intermediate bulkhead in fore hold dispensed with. 6 B4 only.

Pl-Cem Lloyd's C.P. P 44' B 115' F 47'

thickness of Middle Line Strake

50E 560

50E 560

Angles on ditto No.

© 2021

Lloyd's Register
Foundation

17. 10 18