

valve machined off and suitable strips $\frac{1}{4}$ " thick fitted and secured to these edges and this valve restored to a normal working clearance. On valve being placed in position, same checked and all reassembled in proper working alignment. Other minor repairs carried out for particulars see attached report.

W. S.

Noted.

*R.L.G.
28/6/63.*

