

S.S. "WAR DRUMMER".

It is submitted the Owners be informed that when this vessel was built she had 210 fms. of 1-15/16" chain cable placed on board as a war emergency measure, instead of 270 fms. as required by the Rules. This additional length of cable should be placed on board at as early a date as possible.

J.H.N.
11.9.19



© 2021

Lloyd's Register
Foundation

006787-006796-0301