

4m.8.45.

02 JUL 1946

Received by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

AME

"MARY"

REPORT

Drt

No. 7736

of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

A further General Examination L.R. is due 6.46.

No.2 sheer strake plate (s.s.) (E.W.6.44) requires to be renewed and the bulwarks in way, side plating etc. (p.s.amids) and indented poop shell plating (s.s.) require to be dealt with at the earliest opportunity.

The DARTMOUTH Surveyor reports (6.46) vessel placed in floating dock, bottom coated, and on account of damage through heavy weather, a number of defective rivets in centre and side keelsons renewed.

A GENERAL EXAMINATION has been carried out and minor repairs effected.

It is submitted the vessel is worthy to have her present records maintained with record of docking survey 6.46, subject as above, and to have notation of "Examined L.R. 6.46" valid for 12 months assigned.

6.46 Drt., subject

"Examined L.R. 6.46"



© 2021

Lloyd's Register  
Foundation

007059-007071-0002

Floors

Have Watertight Doors been examined and found

efficient? ☒

Transoms, Pointers &amp; Crutches

Timbers of Frame at openings

length

(on

Rule 10

F.