

REPORT OF SURVEY FOR REPAIRS, &c., OF ENGINES AND BOILERS

(Received at London Office 27 Oct 1941)

Date of writing Report 21st Feby., 1941. When handed in at Local Office 21st Feby., 1941. Port of Singapore.

No. in Reg. Book 81457. Survey held at Singapore. Date First Survey 28th Jany., Last Survey 21st Feby., 1941. (No. of Visits 2.)

on the Machinery of the T.S.S. "PING WO". Vessel built at Shanghai. By whom New Engine & S.B. Works, Ltd. When 1922. Engines made at Shanghai. By whom New Engine & S.B. Works, Ltd. When 1922. Boilers, when made (Main) 1922. (Donkey) 1922. Owners Indo-China Steam Nav. Co. Ltd. Owners' Address - Port Shanghai. Voyage -

Last Report No. Port. Particulars of Examination and Repairs (if any) Int. Docking.

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined.

Was a damage report made by anyone else? If so, by whom?

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? No.

Did the Surveyor personally go inside each Donkey Boiler separately and make a thorough examination at this time? No.

If this was not done, state for what reasons Boilers not prepared for survey.

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

State latest date of internal examination of each boiler. Present condition of funnel Good.

Did the Surveyor examine the Safety Valves of the Main Boiler? To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of Donkey Boiler? To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? and of the Donkey Boilers?

Did the Surveyor examine the drain plugs of the Main Boilers? and of the Donkey Boilers?

Did the Surveyor examine all the mountings of the Main Boilers? and of the Donkey Boilers?

Has the screw shaft now been drawn and examined? No. Is it fitted with continuous liner? Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? Yes.

Has shaft now been changed? If so, state reasons.

Has the shaft now fitted been previously used? Has it a continuous liner? Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

State date of examination of Screw Shaft. State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft. O.G's tight

Engine parts, when referred to by numbers, should be counted from forward. Is electric light and/or power fitted Yes.

If so, did the Surveyor examine the generators, motors, switchgear, cables and fuses? No.

Has the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms? No.

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done Complete.

Propellers and outside fastenings examined and found satisfactory.

General Observations, Opinion, and Recommendation:— The machinery of this vessel is eligible, in my opinion, to remain as now classed in the Register Book without fresh record of survey.

Survey Fee (per Section 29) £ : Fees applied for 19. Special Damage or Repair Fee (if any) (per Section 29.) £ : Received by me, 19. Travelling expenses (if chargeable) £ :

TUE. 11 NOV 1941

Committee's Minute Assigned As now

John Hormad Engineer Surveyor to Lloyd's Register of Shipping.



Lloyd's Register Foundation

Insert Character of Ship and Machinery precisely as in the Register Book

In a Certificate required? If so, to be sent to

It is submitted that  
this vessel is eligible to  
remain as CLASSED.

SS No. 1 due 7.41.

L.S.  
5/11/41.



© 2020

Lloyd's Register  
Foundation