

1500, 10, 17.

to Chief Surveyors 24 5-18

Received from Chief Surveyors

SEL'S NAME

Sheelso Montezuma

Report

Sub

No.

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/82.)

re of Survey

When due

The Downton pump & Kedge Anchor have been dispensed with & Spar ceiling has not been fitted in the tween decks.

✱ 100A-1. (Steel)

2 Dks (Steel).

Cell DB a 130' W E 24' 184' 12336. DT. 28' 856' ART 356

FK 6BH Lem. Lysarep. P43 B 126' F 46'

Carrying oil fuel F.P. above 150' F W D.B. D.T.


The Certificate of Classification, to be endorsed  
in tween Dks  
Cargo battens not fitted," and the same  
notation to be printed in the Register Book.

M. 18  
54.5

It is concluded the Owners are agreeable to supply a Downton pump & Kedge Anchor at the termination of the War if requested by the Committee to do so, but the Surveyors should state if this is so

to checking certificates.

see pass this Report to Mr. Mayne for letter to file.



© 2020

Lloyd's Register Foundation

007474-007485-0014