

About 12 ft of Underwater Rail & one end angle ring removed, length

3m, 8, 21.

1

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME

Att Tm to Churton

Report

Lv

No.

89491

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/5/82.)

Nature of Survey

Samay

No. 1

When due

17. 25

Noted

Ref.

29. 17. 25

Lv 301/17/25

The Surveyors should be requested to state the number of anchors now on board



© 2021

Lloyd's Register Foundation

007528-007536-0219

This vessel was ...

... 25

Comin