

Chief Surveyors _____

Received from Chief Surveyors _____

SHIP'S NAME *Steel S.S. "MADURA"*

Report *96*

No. *41562*

For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR.~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

of Survey _____

When due _____

❖ 100 A.1. (Steel)

2 Dks (Steel v Fk's)

Cell DB 403' 1568L Tanks between tunnels 114' 253L, FPT164E, APT69E

FK, 96H, ft Cen, Rkings A.C.P., PAA' B175' F53'

*See Acth
10-1-22*

JH

8-12-21

The Surveyors should be requested to forward the lengths & Capacity of the tanks between the tunnels if fitted

L. Gls 6/11/22

007620-007625-0047



© 2020

Lloyd's Register
Foundation