

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME

CANADOLITE

Rpt.

MHR

No. 5206

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

DAMAGE.

Nature of Survey

Damage through

Heavy weather

now repaired as follows:-

	Shell Plates	Main Frames	R. Frames	Floors & Bracket Floors	Beams	Inner Bottom Plates	Deck Plates
Renewed							
Removed and faired or repaired.....							
Faired or repaired in place.....							


Other items:-

Repairs effected to lifeboats, rails & stanchions, deck fittings etc.

Vessel afloat

It is submitted the vessel is worthy to remain as classed without
record of Survey

ASL
11/1/41



© 2020

Lloyd's Register
Foundation

007 930-007 937-0125