

Rpt. 8.

DISCLOSED SECTION
REPORT OF SURVEY FOR REPAIRS, &c.No. 235
(Received at London Office)
Date of writing Report 19th Jan 1949 When handed in at Local Office 19 Port of Trinidad, B.W.I.
No. in Survey held at Port of Spain, Trinidad Date, First Survey 10th Jan Last Survey 16th Jan 1949
Reg. Book. 61128 on the Wood, Iron or Steel S.S. "H.M. FLEMMER" (No. of Visits 4)
YEAR. 1918 MONTH. 7TONNAGE:— Built at Newport News By whom Newport News, S.B. & D.D. Co. Ltd
GROSS 8208 Owners Panama Transport Co. Owners' Address (if not already recorded in Appendix to Register Book).
UNDER DK. Managers " " " Port belonging to Panama
NET 6103 Destined Voyage Caripio/S. AmericaSurveyed Afloat or in Dry Dock? Afloat Name of Dock — Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)
Cell DBor DBa feet; uE&B feet; f feet
total capacity tons. FPT tons; APT tons; MT feet tons.Only alterations in the existing records of tanks should be inserted.
N.B.—All alterations in the existing records should be underlined.
Last Report, No. 8742 Port BAL

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules and items remaining to complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined —

CHARACTER * for Special Survey, Date of last Survey and of Periodical Surveys.	Machinery and Boiler Surveys (including date of N.B., if any).
4100A1 Nyk	
shelter deck	B.S. 11.47
with freeboard	+LMC 1.45
11.47	2.1.46.
Carrying petroleum in bulk	
Fitted for Oil Fuel	7.18 F.P. above
150°F	SS. Mob 2-1-13 8.41
Society's Freeboard (if assigned) as	SS. 11.46
painted on Ship and now verified	ft. ins.

SS No 1-46

Was a damage report made by anyone else? if so, by whom? No

REPAIRS, OR EXAMINATION AS PER RULE, FOR Repairs to leaks in Sundry leaks found in cargo tanks whilst on voyage to this port from Baltimore via Aruba, St. Thomas & Puerto Rico.

All cargo tanks examined internally except No. 1 and leaks found in following tanks:— No. 1 Port & Starboard, No. 3 Starboard, No. 4 Port & Starboard, No. 5 Port, No. 6 Port, No. 7 Starboard, No. 8 Port & Starboard, No. 9 Port.

Recommended that leaky rivets and seams be welded where possible and cement boxes be fitted as required. A total of twenty six cement boxes were fitted and approx sixty rivets on port side and sixty rivets on starboard side of shell plating welded.

Repairs completed in a satisfactory manner.

SUMMARY OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE

Decks	Bulkheads	Engine Room Skylights	Copper, or Y.M. (State if on Fell.)
Caulking of Decks	Ceiling	Coal Bunkers, Openings, Covers, &c.	When fitted, Month Year
Coamings	Cement or Asphalt	Oil Bunkers	Boats
Beams & Fastenings	Rudder	Scuppers	Masts, Yards, &c.
Outside Plating	Steering gear and its connections	Cargo Hatchways	Condition, how ascertained (State if wedges removed.)
" " in way of sidelights	Windlass	Hatches	Equipment letter
Frames	Have pumps been examined and found efficient?	Planking	Anchors, No. of
Reverse Frames	Have Sluice Valves been examined and found efficient?	Caulking	Cables (State if now ranged)
Longitudinals	Have Watertight Doors been examined and found efficient?	Treenails	" length mean diamr. (on board)
Transverses	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stemson	" Rule length size
Floors	Air and Sounding Pipes	Transoms, Pointers & Crutches	Chain Locker
Keelsons	Doubling Plates under Sounding Pipes	Timbers of Frame at openings	Hawsers & Warps
Stringers		" " at other places	Standing and Running Rigging
Inner Bottom Plating		Stringers, Clamps & Shelves	Sails
Have the Tanks been examined internally?		Salting	
Have the Tanks been tested?		(State if examined.)	

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:— "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1.38," or "to remain as classed and to have record of survey, 1.38, and the notations of ss No. 1-38."

Recommend Vessel remain as Classed in the Register Book

(subject to permanent repairs to above tanks being effected at earliest opportunity.)

Survey Fee (per Section 29)	\$ 120.00	Fees applied for, 17/1/49
Special Damage or Repair Fee (if any) (per Sec. 29)	£	Received by me, 19
Travelling Expenses (if chargeable)	£	
Second Surveyor's Fee (if any)	£	

Committee's Minute

Character Assigned

FRI 29 APR 1949

omit all particulars on repairs

write off

Surveyor to Lloyd's Register of Shipping.



© 2020

Lloyd's Register Foundation

008068 201728 0005

Is Certificate required? If so, to be sent to