

Murta Boiler Rivets

Submitted these rivet
samples to sent to Mr Ripley for
metallurgical investigation

He should be informed that
in 9-38, 143 Rivets is a circumferential
shell seam and 16 in the longitudinal
joints were renewed on account
of broken or cracked points.

Lr 14/12

R. F. 14/1/38

Lloyd's Register
Foundation

008087-008095-0023