

in some cases on the circumferential seam the shell plate edge being bulged opposite the rivet, the holes being stepped from $1/64"$ to $3/32"$.

All the holes were reamed out true before rivets were renewed.

Workmanship and tests satisfactory and the Boiler is now in good condition.

Amey D. Lidgett
SURVEYOR TO LLOYD'S REGISTER
WELLINGTON: N.1.



© 2021

Lloyd's Register
Foundation