

MC

5m, 12, 46.

13 MAY 1946

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME "GIALONG"

REPORT L.A.

No. 12019

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

The class is subject to permanent repairs to indented shell plating (s.s.a. & p.s.f) at the first convenient opportunity and to (a bower anchor and 45 fathoms of chain cable being supplied and the two bower anchors and stream anchor on board being submitted to the Statutory Test).

The SAIGON Surveyor reports (2.48) this vessel placed in dry dock and the bottom found to be somewhat worn by marine growth, as the vessel had not been in dry dock for about 20 months.

The bottom has now been scaled and coated with four coats of paint.

Repairs have been effected to the rudder and minor items.

It is submitted the vessel is eligible to remain as classed with record of docking survey 2.48, subject as above.

2.48 Sgn. subject.



© 2021

Lloyd's Register  
Foundation

27.4.48.

008158-008167-0013