

THROUGH COPY

Lloyd's Register of Shipping,

71, Fenchurch Street, E.C.3.

22nd March, 1951.

assn (S)
DJC

Dear Sirs,

Motorship "JACO"

The Committee have had before them a report from the Society's Surveyor at Willemstad, Curacao, from which it is noted that the above vessel was surveyed in dry dock and the propellers removed to allow the renewal of the zinc ring at the after end of the strut bearing.

During this survey, it was noted that both screwshafts were badly corroded at the top of taper, and the Surveyor therefore recommended that both screwshafts should be renewed before the end of July next.

The Committee have accordingly continued the vessel's class, with fresh record of docking survey 1,51, subject to this matter receiving attention as recommended.

Yours faithfully,

Clerk to the
Classification Committee

Messrs. J. Asmussens Eftf.,
Kristiansgade 22,
COPENHAGEN K.,
Denmark.



© 2021

Lloyd's Register
Foundation

008158-008167-0075