

Limpopo.

Stul 4/1/29

It is concluded that the screw shafts are fitted with outside flanks as stated on the front page of the engine report, not continuous liners as stated on the back of the report, but the surveyors showed otherwise.

WDA 2/8/30