

REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report 1940 When handed in at Local Office 24/4/40

Port of TRIESTE

No. in Survey held at TRIESTE
Reg. Book. 74585

Date, First Survey April 16 Last Survey April 16 1940

(No. of Visits One)

24866 on the Wood, Iron or Steel T.W.N. SC. "FUSITANA"

TONNAGE:-

Built at Trieste

By whom Stabilimento Tecnico

When 1929-3

GROSS 6244

UNDER DEK 5025

NET 3907

Managers

Owners' Address Lloyd Triestino Soc. Anon. di Nav. (if not already recorded in Appendix to Register Book).

Port belonging to TRIESTE

Surveyed Afloat or in Dry Dock? yes

Name of Dock Arsénale

Destined Voyage

Cell D Bor DBa feet; u&B feet; f feet
total capacity tons. FPT tons; APT tons; MT feet tons.

Only alterations in the existing records of tanks should be inserted.

N.B.—All alterations in the existing records should be underlined.

Last Report, No. 12752 Port SRI.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

CHARACTER. * for Special Survey. Date of last Survey and of Periodical Surveys.	Machinery and Boiler Surveys (including date of N.B., if any).
* 100AL 11-39	* LMC. CS. 5-38
SS. Tri. No. 2. - 38	10-38
	DBS. 11-39
	CL. 10-38
	* Lloyd's RMC
	11-39 for Temp
	43°F.

Damage cases where the Surveyor has not made a special damage report he is required to state whether he entered his services for this purpose and to whom and why they were declined

Society's Freeboard (if assigned) as painted on Ship and now verified

Was a damage report made by anyone else? If so, by whom?

AIRS, OR EXAMINATION AS PER RULE, FOR CONDITION

low done: Vessel placed in drydock. Bottom & rudder cleaned, examined and recoated. General examination made of decks, casings, hatches, ventilators and coamings, windlars, steering gear and general equipment. Found in good condition.

Wear & tear repairs:— Shell plates No. 1 of 1st stake below sheer stake (p 25) now doubled for half their length in way of anchor chafing

R. list. - Nothing done at this time. The indented keel & bottom plating fwd. specially examined and found to remain efficient.

MARY OF DAMAGE REPAIRS:-	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:-
Renewed								
Removed and Fair'd or Repaired								
Fair'd or Repaired in place								
PRESENT CONDITION OF THE								
Good	Bulkheads				Engine Room Skylights	Good	Copper, or I.M.	(State if on Felt.)
ing of Decks	Ceiling				Cost Bunkers, Openings, Covers, &c.	"	When fitted, Month	Year
ings	Cement or Asphalt				Oil Bunkers		Boats	Good
s & Fastenings	Rudder	Good			Scuppers	Good	Masts, Yards, &c.	"
de Plating	Steering gear and its connections	"			Cargo Hatchways	"	Condition, how ascertained	For dock
" in way of sidelights	Windlass	"			Hatches	"	(State if wedges removed)	No.
es	Have pumps been examined and found efficient?	Not examined			Planing		Equipment letter	21
se Frames	Have Sluice Valves been examined and found efficient?				Coasting		Anchors, No. of	38 15 18
itudinals	Have Watertight Doors been examined and found efficient?	Not examined			Treenails		Cables (State if now ranged)	no.
verses	Have Ventilators and their Coamings been examined and found efficient?	Yes			Breasthooks & Stemson		" length	Good diamr.
is	Air and Sounding Pipes				Transoms, Pointers & Crutches		" Ryle length	size
Keelsons	Doubling Plates under Sounding Pipes				Timbers of Frame at openings		Chain locker	
Stringers					at other places		Hawser & Warps	Good
Inner Bottom Plating					Stringers, Clamps & Shelves		Sailing and Running Rigging	Good
Have the Tanks been examined internally?					Sailing		Sails	
Have the Tanks been tested?					(State if examined.)			

General Observations, Opinion as to Class, Recommendation, &c.:-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38"

This vessel is in my opinion eligible to remain as classed with fresh record of Survey 4-40. subject to indented keel & bottom plating fwd. being dealt with at Owner's convenience.

Survey Fee (per Section 20) Condition Fee 200-

Special Damage or Repair Fee (if any) £

Travelling Expenses (if chargeable) £ 10-

Second Surveyor's Fee (if any) £

Fees applied for

24/4/1940

Received by me,

19

M Campbell
Surveyor to Lloyd's Register of Shipping.

Committee's Minute

Character Assigned

DUAL CLASS

MAY 21 1940

MAY 12 1940

OMIT CLASS
ON RE-PRINT

© 2021

Lloyd's Register
Foundation

008322-008332-0223