

Received by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

VESSEL'S NAME St. Sc. "TYNEBANK" Rpt. hwc No. 91945

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. 14453 Depth "d" 23'22"
 Framing: Table No. ✓ Description Bull Angle Frames as approved
 Longitudinal No. 36598
 Proportions $\frac{\text{Length}}{\text{Depth}} = \frac{\quad}{\quad} = \underline{11.5}$
 Deck Sheerstrake as approved

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed **✠ 100A.1** "with freeboard," as recommended. The Summer freeboard of ^{see verification form} from centre of disc to top of ~~statutory~~ deck line at deck, now marked on the vessel's sides, to be inserted in the classification certificate, and recorded in the Register Book, and further, the remaining freeboards, as shown on the accompanying verification form to be inserted in the certificate of classification. 1 Dk + Shelter Dk

Cell DB 358'1333t, FPT. 101t, APT 162t.
FK. 7BH (Cell BH to Shelter Dk 6BH to 2nd Dk) ft. cen, Loyds A.C.P.
F. 32'