

20. 3. 19.

Report to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME Steel S.S. "TREMADOW" ex "WAR PICOTEE" Report Gls. No. 38588

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement. - Extract from Sub-Committee's Report, 24592.)

Nature of Survey

When due

The downton pump has been dispensed with for the present as approved in Standard vessels, and it is concluded the present Owners are agreeable to fit same at the end of the War if requested to do so.

Some damage through striking quay wall requires to be permanently repaired at the first opportunity.

100 A.l. (Steel).

1 Dk. (Steel)'

Cell DB 345' 1035t. FPT 125t. APT 210t.

FK. 7 BH. pt. Cem. Lloyd's A. & C.P. P49', B113', F39'.

The Certificate of Classification, to be endorsed "Cargo battens not fitted," and the same notation to be entered in the Register Book.

M
20. 3. 19.

The Surveyors should state the thickness of the poop deck and the length of the doubling fitted at ends of bridge.

W 257/214



© 2021

Lloyd's Register Foundation