

If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the inside of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating

Date of last Survey
Periodical Survey

BY AIR MAIL

COPY

LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

71, Fenchurch Street, London, E.C.3

Telegrams : Committee, Fen, London

Telephone : ROYAL 3551 (6 Lines)

29th June, 1956.

Dear Sirs,

Steamer "KUTUBTARI"

ssn (S)

AH

I acknowledge receipt of your letter of the 15th instant with its enclosure, the contents of which have been noted.

In view of the fact that this ship is now trading outside the limits for which the scantlings and structural arrangements were approved, the Committee at their meeting today, gave instructions for the notation "Class suspended whilst trading outside permitted limits" to be entered against the ship's name in the Society's Register Book. I shall be glad if you will inform the Owners accordingly.

The ship is reported to have changed hands and is now being used for the Andamans Inter-Island Trade for a trial period, which would appear to be outside the limits for the scantlings and structural arrangements which have been approved. refer Ship Plans' Memo of 5.3.55.

Yours faithfully,

In a copy Clerk to the dated 12.6.56 to our Bombay Surveyors Classification Committee. It may be some time yet before a decision is made as to whether or not the ship will continue to the Andamans Inter-Island Trade.

In view of the foregoing IT IS SUBMITTED for consideration whether the class might be suspended as suggested in our letter of 5.3.55 to the Bombay Surveyors, dated 12.6.56. Yours sincerely,
The Surveyors,
BOMBAY.



© 2020

Lloyd's Register
Foundation