

5c.12.25.

F.E.

Received by Chief Ship Surveyor .....

Received from Chief Ship Surveyor .....

VESSEL'S NAME Stl T.S. SURINAM Rpt. Bel No. 10179

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

<sup>1st</sup> Long Transverse No. 5200

Depth "d" 14.25

Framing: Table No. ✓

Description Bulb angle frames as approved

<sup>2nd</sup> Longitudinal No. 23075

Proportions Length  
Depth =

Deck Sheerstrake as approved



Revised Rules

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

✠ 100 A.1. (Steel). Carrying Petroleum in bulk.

1 D<sup>c</sup> (Stl).

Side tanks a 72' + 104' 1824t, F.P.T. 83t, A.P.T. 75t.

F.K., T.B.H., pt cem, Lloyds A.C.P.

P 69', TRUNK 220', F 36. machy aft.

The Surveyors should be requested to forward the repairs



© 2021 Lloyd's Register Foundation  
008759-008764-0054

J. 3.6.29.

Spacing .....

24