

DISCLOSED  
SECTION  
No.

DISCLOSED  
SECTION  
No.

DISCLOSED  
SECTION  
(Received at London Office)

25 APR 1955

No. 30120

# REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report... 19<sup>th</sup> April 55. When handed in at Local Office... 22-4-1955 Port of Antwerp  
No. in Reg. Book. Survey held at Antwerp Date, First Survey 18<sup>th</sup> April 55 Last Survey 18<sup>th</sup> April 55.  
(No. of Visits... ONE...)

958885 on the Wood, Iron or Steel 8PS. "PARAPORTI" (EX RALDO)  
TONNAGE: Built at Sunderland By whom Bartram & Sons Ltd When 1925 2  
GROSS 4687 Owners Paraportti Compania Naviera S.A. Owners' Address  
UNDER DK 4277 Managers Port belonging to Puerto Limon.  
NET 2851

Surveyed Afloat or in Dry Dock? Afloat. Name of Dock 238 Berth Antwerp Dock Destined Voyage  
Cell D B or D B a feet; u E & B feet; f feet  
total capacity tons. FPT tons; APT tons; MT feet tons.

Only alterations in the existing records of tanks should be inserted.  
N.B. All alterations in the existing records should be underlined.

Last Report, No. 130115 Port London

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules and items remaining to complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Society's Freeboard (if assigned) as painted on Ship and now verified } ft. ins.

Was a damage report made by anyone else? if so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR GROUNDING.

Ship stated to have grounded on Sandetti Banks on 16<sup>th</sup> April 1955 whilst on voyage from Huelva to Antwerp.

Ship surveyed whilst lying afloat at 238 Berth Antwerp in loaded condition.

Soundings taken throughout ship and verified with those in log book, (Note:- log book stated all tanks empty) no difference being noted.

Steering gear examined and found satisfactory.

Master stated ship proceeding to Newcastle-on-Tyne direct from Antwerp for dry docking.

Interim cert. issued - copy attached.

Copy of interim cert. forwarded to Newcastle Surveyors.

SUMMARY OF DAMAGE REPAIRS :-	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items :-
Renewed ...								
Removed and Fair'd or Repaired								
Fair'd or Repaired in place ...								

## PRESENT CONDITION OF THE

Decks	Bulkheads	Engine Room Skylights	Copper, or Y.M. (State if on felt.)
Caulking of Decks	Ceiling	Coal Bunkers, Openings, Covers, &c.	When fitted, Month Year
Coamings	Cement or Asphalt	Oil Bunkers	Boats
Beams & Fastenings	Rudder	Scuppers	Masts, Yards, &c.
Outside Plating	Steering gear and its connections	Cargo Hatchways	Condition, how ascertained (State if wedges removed.)
" " in way of sidelights	Windlass	Machinery	Equipment letter
Frames	Have pumps been examined and found efficient?	Planing	Anchors, No. of
Reverse Frames	Have Sluice Valves been examined and found efficient?	Caulking	Cables (State if now ranged)
Longitudinals	Have Watertight Doors been examined and found efficient?	Treenails	" length mean diamr. (on board.)
Transverses	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stemson	" Rule length size
Floors	Air and Sounding Pipes	Transoms, Pointers & Crutches	Chain Locker
Keelsons	Doubling Plates under Sounding Pipes	Timbers of Frame at openings	Hawsers & Warps
Stringers		" " at other places	Standing and Running Rigging
Inner Bottom Plating		Stringers, Clamps & Shelves	Sails
Have the Tanks been examined internally?		Salting	
Have the Tanks been tested?		State if examined	

## General Observations, Opinion as to Class, Recommendation, &c.:

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

This ship is in efficient condition and eligible in my opinion to be retained as now classed without fresh record of survey subject to special examination of bottom shell at her next drydocking and all other conditions of class to be dealt with as previously recommended.

Survey Fee (per Section 23)		Fees applied for, 22-4-1955
Special Damage or Repair Fee (if any) (per Sec. 23)	£. : 2100.-	Received by me, 19.-
Dwelling Expenses (if chargeable)	£. : 125.-	
Second Surveyor's Fee (if any)		

Committee's Minute Not for Classing Office See Ctee Minute 29/4/55  
Character Assigned

Surveyor to Lloyd's Register of Shipping.

Lloyd's Register Foundation

008773-008777-0163