

Msl Rpt No 10,677.

"MATELOTS PILLIEN ET PEYRAT"See also
22/6/48.

IT IS SUBMITTED before this case receives consideration, the Surveyor be informed that his statement on page 2 of his report, that a watertight door is not fitted to either of the new bulkheads on frames 77 and 87, is not understood since such an arrangement is not in accordance with the Rules nor with the plans approved for these alterations.

If not already fitted, a W.T. door must be provided on one of these bulkheads or, alternatively, *already done,* the opening in way of the tunnel closed by steel plates and made watertight at the very earliest opportunity.

The Surveyor should be requested to furnish his remarks and recommendations by air mail.

© 1901
22.6.48.Lloyd's Register
Foundation

008831 - 008838 - 0029