

5m, 9, 35.

1

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME Steel Screw "DARLENY" Report Grk. No. 20311

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR.~~

(In cases which have to be submitted to the Cladding Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Cladding Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/82.)

Nature of Survey First Entry & Damage When due --


100AL 'With Freeboard'

1 Dk. & Shelter Deck.

Cell. DB 368' 1207t, FPT 127t, APT 206t.

FK, One Intermediate Bulkhead dispensed with Coll. BH to Shl. Dk.
5 BH to 2nd Dk., pt. Cem., Lloyd's A & CP.

F 33'



© 2021

The Glasgow Surveyors should be informed it is concluded that the outboard channel vertical strut of the bracket floors is as approved.

Foundation
[Handwritten initials]
 11.2.37

ES IN S

3
3
Ex 32
2x 32
32
5
2
6
6
32
78
47
6 A
17
78

7 32