

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 19... When handed in at Local Office 19... Port of London DISCLOSED BOX 53 Top. Date, First Survey Last Survey 19

No. in Reg. Book. 51031 Survey held at Ferro. Concrete "Bretehive" on the Wood, Iron or Steel Date, First Survey (No. of Visits) Master -

TONNAGE:- GROSS 708 BUILT at Greenock By whom Scottish Concrete Ship Co. Ltd. When 1920 3 UNDER DECK 655 Owners A. Henniksen Port belonging to Hangesund NET 658 Owners' Address - Managers -

Surveyed Afloat or in Dry Dock? Name of Dock Destined Voyage Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

WB=CellDBorDBa feet; uE&B feet; f feet; total capacity tons. FPT tons; APT tons; MT feet tons. N.B.-All alterations in the existing records should be underlined.

Last Report, No. 73586 Port HWT

Annual survey 5.22 Coasting Great Britain & Ireland (except west coast - Cork to Portland Head) and Continent - from Brest to Hamburg, also Baltic Ports April to October. Subject to Annual Survey - Experiencia.

Was a damage report made by anyone else? If so, by whom?

IRS, OR EXAMINATION AS PER RULE, FOR

OF DAMAGE REPAIRS:-	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:-
newed ...								
moved and Faired or Repaired ...								
red or Repaired in place ...								

CONDITION OF THE	State if Tanks have been examined inside	Dblg. Plates under Sounding Pipes	Copper, or Y.M. of Wood Vessels
of Decks	State if Tanks now tested	Engine Room Skylights	(State if on Felt.)
Bulkheads		Coal Bunkers, Open'gs, Lids, &c.	When put on, Month Year
Ceiling		Scuppers	Boats
Fastenings	Cement or Asphalt (State which.)	Cargo Hatchways	Masts, Yards, &c.
ating	Rudder	Hatches	Condition, how ascertained
f ditto	Steering gear and its connections	Planking of Wood Vessels	(State if wedges removed)
ts & Crutches	Windlass	Caulking ditto	Sails
	Have Pumps now been examined and found efficient?	Treenails ditto	Equipment letter
	Have Sluice Valves now been examined and found efficient?	Breasthooks & Stemson ditto	Equipment letter
ames	Have Watertight Doors now been examined and found efficient?	Transoms, Pointers, & Crutches ditto	Anchors, No. of
	Have Ventilators and their Coamings been examined and found efficient?	Timbers of Frame at openings ditto	Cables (State if now ranged)
om Plating		Ditto ditto at other places ditto	" length size (on board)
		Stringers, Clamps & Shelves ditto	" Rule length size
		Salting (State if examined)	Hawser & Warps
			Standing & Running Rigging

ral Observations, Opinion as to Class, Recommendation, &c.:-


State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon a survey, thus, for example:- "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,15," or "to remain as classed and to have record of survey, 1,15, and the notations of ss No. 1-15 and ptND15, &c."

(per Section 20) ...	£	:	:	Fees applied for.
Damage or Repair Fee (if any) ...	£	:	:	19
Expenses (if chargeable) ...	£	:	:	Received by me.
Surveyor's Fee (if any) ...	£	:	:	19

Committee's Minute

Character Assigned

Surveyor to Lloyd's Register of Shipping.



Lloyd's Register Foundation

008425-008937-2301