

to Chief Surveyors _____

Received from Chief Surveyors _____

SEL'S NAME _____

Steel S.S. "WAR ROTHER". _____

Report _____

Grk. _____

No. 17423

For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/22.)

Date of Survey _____

When due _____

* 100 A.1. (Steel).

1 Dk. (Steel). Well Dk.


Cell DB. 190' 395t. APT 50t.

FK. 4 BH. Cem. Lloyd's A. & C.P. Q79', B56', F27'.

Certificate of Classification, to be endorsed
"cargo battens not fitted," and the same
notation to be printed in the Register Book.

It is concluded the hand pumps ^{Hand pumps not fitted see below} in holds are 5" diameter. ^{20. 3. 19.}

Surveyors should state if this is so



© 2021

Lloyd's Register
Foundation

1701021-009029-0124