

# DISCHARGED SECTION REPORT OF SURVEY FOR REPAIRS, &c.

(Received at London Office)

No. 109136A

Date of writing Report 19... When handed in at Local Office 19... Port of London

No. in Reg. Book 28858 Survey held at on the Wood, Iron or Steel M.Y. "FLORIDA MARU" Date, First Survey Last Survey 19

TONNAGE:- Built at Kobe By whom Kawasaki Drydock Co When 1925 3  
GROSS 5845 Owners Kawasaki Kisen K.K Owners' Address  
UNDER DK. 5333 Managers Port belonging to Kobe  
NET 3651

Surveyed Afloat or in Dry Dock? Name of Dock Destined Voyage  
CellDBorDBa feet; uE&B feet; f feet  
total capacity tons. FPT tons; APT tons; MT feet tons.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)  
CHARACTER: \* for Special Survey, Date of last Survey and of Periodical Surveys.  
Machinery and Boiler Surveys (Including date of N.B., if any).  
+100 RI 5.40  
+Lmc 08.8.36  
D.B.S 5.40  
-5.40  
ss. Kob No 3-11.38 02.5.40  
Oil Engine

Last Report, No. 6927 Port Uka  
In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined.  
Society's Freeboard (if assigned) as painted on Ship and now verified } ft. ins.

REPAIRS, OR EXAMINATION AS PER RULE, FOR  
Was a damage report made by anyone else? if so, by whom?  
SUMMARY OF DAMAGE REPAIRS :-  
Renewed ...  
Removed and Faired or Repaired ...  
Faired or Repaired in place ...

PRESENT CONDITION OF THE

Decks	Bulkheads	Engine Room Skylights	Copper, or Y.M. (State if on Belt.)
Paulking of Decks	Ceiling	Coal Bunkers, Openings, Covers, &c.	When fitted, Month Year
Coamings	Cement or Asphalt	Oil Bunkers	Boats
Beams & Fastenings	Rudder	Scuppers	Masts, Yards, &c.
Outside Plating	Steering gear and its connections	Cargo Hatchways	Condition, how ascertained (State if wedges removed.)
" " in way of sidelights	Windlass	Hatches	Equipment letter
Frames	Have pumps been examined and found efficient?	Planking	Anchors, No. of
Reverse Frames	Have Sluice Valves been examined and found efficient?	Caulking	Cables (State if now ranged)
Longitudinals	Have Watertight Doors been examined and found efficient?	Treenails	" length (on board) mean diam.
Transverses	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stemson	" Rule length size
Floors	Air and Sounding Pipes	Transoms, Pointers & Crutches	Chain Locker
Belsons	Doubling Plates under Sounding Pipes	Timbers of Frame at openings	Hawsers & Warps
Stringers		" " at other places	Standing and Running Rigging
Inner Bottom Plating		Stringers, Clamps & Shelves	Sails
Have the Tanks been examined internally?		Salting (State if examined.)	
Have the Tanks been tested?			

General Observations, Opinion as to Class, Recommendation, &c. :-  
State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example: "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

Survey Fee (per Section 29) £ : : Fees applied for, 19  
Special Damage or Repair Fee (if any) (per Sec. 29) £ : : Received by me, 19  
Travelling Expenses (if chargeable) £ : :  
Second Surveyor's Fee (if any) £ : :

Committee's Minute FRI. 21 NOV 1941  
Character Assigned  
Surveyor to Lloyd's Register of Shipping  
Friday 28th November 1941  
Classing Committee's decision confirmed  
H.D. Foundation

10m. 2. 1. 1. - Transfer Ink. (The Surveyors are requested not to write on or below the space for Committee's Minutes.)

Is Certificate required? If so, to be sent to

009640 - 009649 - 0228