


"HOLLAND"

IT IS SUBMITTED the Durban Surveyors be informed that  
it is considered the tube plate flanges should be cropped and  
part renewed where cracked, in addition to the renewal of the  
combustion chambers as recommended.



23. 10. 50.



© 2021

Lloyd's Register  
Foundation

009067-009073-0130