

If the liner does not fit tightly at the part between the liners ..... Is an approved Oil Gland or other appliance fitted


Engine No. 448550/58 Made by Humboldt - Bay  
Boiler For W.S. Bailey & Co. Law 291.

Dust Report No. 232

It is submitted that a copy of this Report be  
~~forwarded to the~~ ~~Surveyors for their~~  
~~returned~~ ~~guidance and for completion.~~  
retained pending completion.

Date

6-4-38



© 2021

Lloyd's Register  
Foundation

009116 - 009121 - 0026

Copy Rpt sent N.Y.

1m, 6.3%

8 APR 1938

Are the Blow Off Cocks fitted with a spigot and