

The class is subject to the centre furnace of the centre boiler being specially examined at the next B.S.

COPY.

Lloyd's Register of Shipping,

71, Fenchurch Street, E.C.3.

13th February, 1951.

Classn.

GEHM

Dear Sirs,

S.S. "REG III" ex "ALASKA"

I have to acquaint you the Committee have had before them a report from the Society's Surveyor at Alexandria from which it is noted that the Boiler Survey which became due on this vessel in July last was partly held in December last.

The Surveyor reported that the centre boiler manhole door studs were found bent and that one stoppered tube was fitted in the starboard boiler. He recommended that the manhole door studs and stoppered tube should be renewed before the end of March next.

The Committee have accordingly continued the vessel's class subject to these matters receiving attention by the time stated, and to entitle the vessel to a fresh record of B.S. 12,50 the port boiler remains to be examined and all safety valves adjusted, in addition to the above mentioned repairs.

I have to add that the vessel's class is also subject to a fractured shell plate (F.2 on the starboard side aft), previously repaired by electric welding, being specially examined by January 1951.

In the circumstances, I shall be obliged if you will let me know what arrangements you propose making for these matters to receive attention.

Yours faithfully,

Copies sent Ham. & Bgn.

Clerk to the
Classification Committee.

Messrs. Helmut Thimm & Co.,
Jungfernstieg 30,
HAMBURG 36.



Lloyd's Register
Foundation

009139-60143-0026