

liner does not fit tightly at the part between the bearings in the stern tube, is the space covered with a plastic material insulating  
is fitted in the shaft lapped or protected between the liners Is an approved Oil Gland or other

Made by *A. Borsig Berlin*  
*Makskovs no. 57.*

*Stettin* Report No. *1027*

*Copies of these* *Sent*  
It is submitted that ~~this~~ Report be returned to

the *Cpu.* Surveyors for their guidance and  
for completion.

*ies Sent*  
*with original*  
*of reports etc*  
*24/12/31*



Date *2/10/37*  
*009232 - 009234 - 0023*

ment to another Is the Shaft Lined with ...  
V BOILERS &c — (Letter for record) Total Heating Surface of Boilers *290*