

Surveyors

Received from Chief Surveyors

NAME Steel S.S. MONTCALM

Report 9/5

No. 41592

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

in cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/02.)

Agency

When due

100 A-1. (Steel) Shelter Deck with foreward

Dks (Steel) 2 Shelter Dk (Steel w/s) 3rd Dk (Steel) in holds
F.W. Tanks at Sides of Tunnel 40' 524T 27.1.22.
12 DB 47u 2358T, IT 37' 10 7/4t, FPT 181t, APT 160t

12 BH to Shelter Dk, pt Cen, Wly 1/2 A & CP, B & F 490' on Shelter Dk
Upper B 265'

Date of build ~~4.20~~ 12, 21

of Build See report. See letter 26-1-22

cluded three rows of pillars are fitted and not two as stated but the
Should be requested to state if this is so; they should also be requested to forward
the and Capacity of the F.W tanks at sides of tunnels.

[Handwritten signature]
2-1-22

009522-009526-0123

Lloyd's Register
Foundation