

to turbo-generator has
been efficiently installed
aboard the vessel but
remains to be examined
under full working conditions.
Surveyor advised.

Wm. C. Thomas



© 2020

Lloyd's Register
Foundation

00455700 9564-0233