

18 JUL 1957

Received from Chief Ship Surveyor

SHIP'S NAME "TINTERN ABBEY" REPORT Cff. No. 60146

Outstanding Conditions of Class: Subject to sternframe solepiece (E.W. & reinforced 10,55) being specially examined next drydocking, and to indented side shell plating etc. (p & s.f.) being dealt with as necessary next Special Survey.

Endorsement of Class (B) (As before ~~or None~~)

Nature of Present Survey: (Afloat and in dry dock)

Drydocking: Repairs on account of damage due to navigating in ice, previously reported.

Recommendation: SUBMITTED NOTATION of 'DS 5,57' be assigned as recommended, subject to sternframe solepiece (E.W. & reinforced 10,55) being specially examined next drydocking, without other conditions but with Endorsement of Certificate.

DS 5,57 Subject
Without.

ENDORSEMENT OF CERTIFICATE

Shell plates F.5 (p & s), D.2, E.5
F.3 & 4 (s.s.) indented.



© 2021

Lloyd's Register
Foundation