

30th September, 1958

HONG KONG

403, 422 - As recommended.

C. 14416, 428 - As recommended.

316 "ELISABETH BAKKE" As recommended. I shall be glad you will forward a sketch, showing the repairs carried out to the sternframe.

"EGEI II" 14394 Assignment of class in this case has been deferred, pending the receipt of a satisfactory report of General Examination on the ship's arrival in its trading area, and in this connection I would draw your attention to the Freeboard letter of the 22nd September.

It is concluded that BH 42 is Non-watertight, the diameter of the rudder head is $3\frac{1}{2}$ " , the rudder mainpiece is 4" outside diameter tube, the length of bridge aft is 36', all as shown on the plans and not as reported. It is also concluded that the towline and hawsers and warps have been tested as required by the Rules.

© 2021
Lloyd's Register
Foundation
009789-009795-0241