

30 APR 1962

Received from Chief Ship Surveyor.....

SHIP'S NAME "MEDINA PRINCESS" REPORT B.As No. 33722

EA

Outstanding Conditions of Class: Subject to shell plates G.8 & 9 from aft in way of No.4 hold and F.7 & 8 (p.s.) being specially examined and dealt with as necessary next drydocking.

S.R.L. Appendix. (As before or None)

Nature of Present Survey: (Afloat and in dry dock)

Deferred repairs to leakage.

Recommendation: SUBJECT as above and to after peak tank being tested for leakage by 6,62.

As Now Subject.

IN S.R.L. APPENDIX.

Indents in shell plating (s.s).

Tank top plating in Nos.1 to 5 holds and tunnel

side plating in No.4 hold indented.

Upper deck plating wavy in way of welded butts.



© 2021

Lloyd's Register
Foundation

ABM,
30/4/62