

2m. 9.18.

1

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME Steel S.S. "LYNCHBURG". Report Phl. No. 3035

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

Nature of Survey _____ When due _____

The Downton pump and kedge anchor have been dispensed with
as a War Emergency Measure.


Owners, United States Shipping Board.

* 100 A.1. (Steel).

1 Dk. (Steel).

Cell DE. 254' 702t. FPT 106t. APT 137t.

FK. 5BH. Cem. A. & C.P. P29', B75', F29'.


31. 12. 18.



© 2021

Lloyd's Register
Foundation

009976-009985-0065

BEAT