

- 32 Essential Independent Pumps (Identify by position).....
- 33 Bilge, Ballast & Oil Fuel Suction Lines, Fittings & Controls.....
- 34 Have the remaining Piping Arrangements & Fittings in the machinery space been examined as considered necessary?.....
- 35 Fresh Water Coolers..... 36 Lub. Oil Coolers..... 37 Heaters (state service).....
- 38 Independent Air Compressors, Cooleers & Safety Devices.....
- 39 Air Receivers & Safety devices - Main..... 40 Auxiliary.....
- 41 Oil Fuel Tanks (Not forming part of hull structure).....
- 42 Evaporators..... 43 Have Evaporator Safety Valves been tested under steam?.....
- 44 Steering Machinery..... 45 Windlass..... 46 Fire Extinguishing Arrangements.....

~~AUXILIARY ENGINES (Identify by position).....~~

PROPULSION		ELECTRICAL EQUIPMENT	
PORT	STARBOARD	PORT	STARBOARD
a Generators.....		AUXILIARY EQUIPMENT	
b Exciters.....		l Generators & Governors.....	
c Air Coolers.....		m Motors.....	
d Motors.....		n Switchboards & Fittings.....	
e Air Coolers.....		o Circuit Breakers.....	
f Control Gear, Cables, etc.....		p Cables.....	
g Insulation Resistance.....		q Insulation Resistance.....	
h Insulating Oil Test.....		r Steering Gear Generators and Motors.....	
i Overspeed Governors.....		s Navigation Light Indicators.....	
j Magnetic Couplings.....			
k Air Gap.....			

BOILERS OPENED UP & EXAMINED (Identify by position and state latest date of internal examination of each boiler)

MAIN (one boiler only) 29/7/57..... AUXILIARY, DONKEY or PRESS.....

Superheaters.....

Safety Valves Good.

Mountings, Doors & Fastenings Good.

Safety Valves Adjusted to { Sat. 200 lbs. per sq.in.
Spt. Good.

Boiler Securing Arrangements Good.

Main Economisers..... Exhaust Gas Heated Economisers.....

Steam Heated Steam Generators..... Steam Generator Safety Valves Adjusted to Yes

Were Oil Burning System & Remote Controls examined working in accordance with Rules?..... Forced Circulating Pumps.....

Have Saturated Steam Pipes in cylindrical boiler smoke boxes been examined as required by Rules?..... Funnel Good.

EXAMINATION & TESTING OF STEAM PIPES (State material)

Main..... Auxiliary (over 3 in. bore).....

Were Copper Pipes annealed?..... Have Saturated Pipes in cylindrical boiler smoke boxes been tested?.....

PARTICULARS OF DEFECTS & REPAIRS, ETC. (Damage repairs should be detailed separate from wear and tear repairs; state what action has been taken regarding items which are subjects of class)

Boiler examined internally and externally 29th July 1957 and found or put in good order. All mountings taken apart and found or put in good order. Boiler subjected to a hydrostatic test of 275 lbs. per sq.in. on the 16th August 1957, and found in good order.

Repairs Effected:- Two plain tubes renewed.

LEAVE THIS SPACE BLANK

Survey fees ... £12. 12. 0

Damage fee ...

Expenses... ..

Date when A/c rendered... 16/8/57.