

7 APR 1959

Received from Chief Ship Surveyor.....

NAME "ABQAIQ" REPORT Gen. No. 24034

Existing Conditions of Class: NONE.

Assessment of Certificate (~~As before~~ or None)

Result of Present Survey: (Afloat and in dry dock)

Drydocking: Wear and tear repairs:

Deferred repairs to indented side shell plating on account of
unknown damage.

Recommendation:

SUBMITTED record of 'DS 3,59' be assigned,
subject to indented shell plate 2nd strake
below No.4 (p.s. from aft) being specially
examined and dealt with as necessary next
drydocking.

DS 3,59 Subject



© 2021

Lloyd's Register
Foundation

010236-010245-0306