

Received from Chief Ship Surveyor..... 18 JUL 1958

SHIP NAME "DINGLEDALE" REPORT Bom. No. 12738
AR.

Existing Conditions of Class: None.

Reversal of Certificate (As before ~~XXXXXX~~)

Surveys due: SPECIAL SURVEY (C) due 12,58.

Particulars of Present Survey: (Afloat and in dry dock) Drydocking; Special Survey; W & T repairs to shell and cargo tank internals including repairs to indented shell plates (part appendix item); reported 15 fathoms of chain cable on board worn to renewal size - removed.

Special Features: None.

Interim Certificate in order (Yes-~~NO-NONE~~)

Surveys Outstanding: (If any for S.S.) None.

Work completed ~~xxx~~

Recommendation: SUBMITTED record of 'DS 6,58' and the Notation of 'S.S. Bom. 6,58' be assigned as recommended, SUBJECT to 15 fathoms of chain cable being supplied at the earliest opportunity. (See O. 16/31/10/58)

DS 6,58.
S.S. Bom. 6,58. Subject.

S.R.L. APPENDIX (AMENDED)
No.2 keel plate from fwd. forecastle sheerstrake etc. (s.s) and poop side plating (p.s.) indented.

IT IS FURTHER SUBMITTED the Owners should be advised of the condition of class and be requested to state what arrangements they are making to deal with this item.

See letter 30.7.58



© 2021

Lloyd's Register Foundation

E. K. Howe