

15 MAR 1961

SHIP'S NAME "MARINE NAVIGATOR"

REPORT

SMK

No. 1694

EA

Outstanding Conditions of Class:

to

SUBJECT to shell plate G.15 (p.s) stringer plate of deep tank top and framing in way, also to shell plate F.19 and framing in way (p.s) being specially examined and dealt with as necessary by the Special Survey.

ACTION is DEFERRED for Special Survey (C) (due 8,60) by 8,61.

S.R.L. Appendix. (~~As before~~ None)

Nature of Present Survey: (Afloat ~~and in dry dock~~)

Deferred repairs to damage caused by contact.

AS ABOVE

Recommendation:

SUBJECT to indented shell plating in 4th and 5th strakes below sheer in way of No.2 hold (p.s.) being dealt with as necessary at the next drydocking, but further ACTION continue to be DEFERRED for Special Survey by 8,61.

SUBJECT.



© 2021

Lloyd's Register
Foundation

010755-010765-0268