

"MYTONGATE"Electrical Equipment.Special Survey, Repairs and Additions.

The engine room was rewired, various repairs and partial rewire of accommodation and navigation circuits.

The generators and main switchboard were repaired.

An additional 3 KW reconditioned shaft driven generator and extra panel on the main switchboard with volt ammeter, switches, fuses etc. for this generator were fitted.

The voltage regulator on the above generator is faulty and is to be changed in about three weeks time, but the machine being used for lighting only is considered satisfactory in the meantime.

The current supplying the navigation circuits is at present taken from the accommodation and a new cable direct from the main switchboard is to be fitted.

The electrical equipment was operated under working conditions with satisfactory results and apart from the foregoing is considered satisfactory.

The insulation resistance of all circuits and apparatus was examined and found good.

The foregoing examination may be considered for a special survey.

S.S.

Fee:- £ 5: 0: 0d.

Repair & 4: 4: 0d.
additions

W. G. Connell



© 2021

Lloyd's Register
Foundation