

19 SEP 1962

Received from Chief Ship Surveyor.....

SHIP NAME "CHOPIN"

REPORT

STN.

No. 1019

EA

Standing Conditions of Class:

SUBJECT to damaged spare bower anchor on board being renewed at the earliest opportunity and to the 10th length of anchor chain cable (s.s.) being tested at the earliest opportunity.

R.L. Appendix. (As before ~~or None~~)

Structure of Present Survey: (Afloat and ~~in dry dock~~)

Equipment: Supply and verification of a bower anchor - part deferred item as above.


Recommendation:

SUBMITTED the ship is eligible to remain as classed, subject to the 10th length of anchor chain cable being tested at the earliest opportunity, without other conditions.

As Now Subject
without.

IN S.R.D. APPENDIX

(Main structure partly of P.403 Steel).



© 2021

Lloyd's Register
Foundation

010797 - 010804 - 0030