

propeller boss. If the liner is not tight at the joint between the bearings in the stern tube, is the space charged with a plastic material insoluble in water.
If the liner does not fit tightly at the joint between the bearings in the stern tube, is the space charged with a plastic material insoluble in water.

Princess Joan

Gr. 50330.

It is concluded that the thrust shafts are $9\frac{7}{8}$ diameter not $7\frac{7}{8}$ as reported and that the shell seam riveting of the Boiler is as approved but this should be confirmed.

Gr. 3015730

J. H. 22/4/30

010846-010857-003a

Are all Sea Connections fitted direct on the skin of the ship

Are they fitted with valves or Cocks

Are the Overboard Discharges a

4/6. Are the Overboard Discharges a