

No. 5497

REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report Sept. 15 1956 When banded in at Local Office _____ 19____ Port of LOS ANGELES HARBOR, CALIFORNIA
No. in Reg. Book. Survey held at SAN PEDRO, CALIFORNIA Date First Survey July 18'56 Last Survey Sept. 13, 1956
74164 on the ~~Wood~~ Iron or Steel MV "POZA RICA" (No. of Visits fourteen)

TONNAGE:— Built at Trieste By whom C. R. D. Adriatico YEAR. MONTH. 1938
GROSS 7884 Owners Petroleos Mexicanos Owners' Address _____
UNDER DK. --- Managers --- (if not already recorded in Appendix to Register Book).
Port belonging to Tampico

Surveyed Afloat or in Dry Dock? Both Name of Dock Todd #2 Dock Destined Voyage

Cell DB or DBa _____ feet; uE & B _____ feet; f _____ feet } Particulars of Classification (which must be inserted
total capacity _____ tons. FPT _____ tons; APT _____ tons; MT _____ feet _____ tons. } precisely as in Register Book & Supplements)

Only alterations in the existing records of tanks should be inserted.

B.—All alterations in the existing records should be underlined.

Report, No. 5145 Port L.A.

Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) separated from Repairs due to other causes; and besides being detailed in the body of the report, should be in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars early stated in the space provided on the back of this form. State also the dates and initials of any letters in case.

ses where the Surveyor has not made a special damage report he is required to state whether he is services for this purpose and to whom and why they were declined. To Owners Rep-

tive, not required.

Was a damage report made by anyone else? if so, by whom? No

EXAMINATION AS PER RULE, FOR Condition Docking & repair of damage to shell plating & internals of Forward Cargo Tanks (No.7) time and place stated not recorded.

E:- Vessel placed in drydock, the hull, bottom, stern frame & rudder cleaned, examined, & now placed in good condition and recoated.

cargo tanks, port, center & starboard, cofferdams fore & aft, fore & aft peak tanks, dry-rward, all examined internally. Tween decks & peak spaces forward & aft, machinery spaces broom examined.

s, casings, hatchways, ventilator casings, fore & aft gangway, rudder quadrant, tiller, gear & its connections, windlass, watertight doors & general equipment examined, found or in satisfactory condition.

P. T. O.

*DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:—
— — — — —	2				3			
nd Fair'd or Repaired		22						
Repaired in place								

DITION OF THE		Satisfactory.	Engine Room Skylights	'good	Copper, or Y.M.	
good			Coal Bunkers, Openings, Covers, &c.	---	(State if on Felt.)	
---			Oil Bunkers	good	When fitted, Month	Year
good			Scuppers	"	Boats	good
"			Cargo Hatchways	"	Masts, Yards, &c.	good
"			Hatches	"	Condition, how ascertained	from deck
way of sidelights	---		Planking		(State if wedges removed.)	
good			Caulking		Equipment letter	C
---			Treenails		Anchors, No. of	3B 1S
good			Breasthooks & Stems		Cables (State if now ranged)	yes
"			Transoms, Pointers & Crutches		" length	300 mean diam.
"			Timbers of Frame at openings		" (on board)	300 size
"			Stringers, Clamps & Shelves		" Rule length	300 size
"			Salting		Chain Locker	good
ing	"		(State if examined.)		Hawseers & Warps	complete.
een examined internally?	yes				Standing and Running Rigging	---
een tested?	as noted.				Sails	---

Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon survey, thus, for example:—"_____ to remain as classed in the Register Book *without fresh record of Survey*," "to remain as classed and to have record of 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

essel is in satisfactory condition and eligible, in my opinion, to remain as classed, with record of L. An. 9/56, subject to echo sounding device in aft pumproom remaining disconnected service until moved to a safe position. (3 electrical)

Section 29) _____	\$	60.00	:	Fees applied for, _____ 19____ Received by me, _____ 19____
Repair Fee (if any) _____	\$	200.00	:	
_____ (if chargeable) _____	\$	16.00	:	
SAF _____	\$	18.00	:	
Fee (if any) _____	\$:	:	
expenses _____		10.00	:	

Committee's Minute

Character Assigned 9.56 L.A. Subject

(N) As Unit
DBS 9-56 and TS (CL) 8-56

Surveyor to Lloyd's Register of Shipping.

Lloyd's Register
Foundation

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so rough that it will spread the ink, or to cause it to run through to the other side.

Vessel drydocked August 20 - 27th, 1956.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.

Certific
ile the
it is to
to be h
in the
s Comm

10M 4-52

ed, doubling
al fracture

ved, longer doubler 66" X