

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegrams: Committee, London, Telex
Telex No.: 24305

Telephone: ROYal 9166

24th October, 1961.

C
WK/EMD

Dear Sirs,

Steamer "DOM JOSE" ex "SAO PAULO"

Before your report No.8075 receives the consideration of the Committee I have to inform you that before the class of this ship was expunged in January, 1960 the class was subject to indented shell plates H.3 & 4, G.3 & 4, (port side), also indented stern plating (starboard side) being examined and dealt with as necessary on completion of the Special Survey, and to leaky shell plating in way of aft peak tank (port side) and below condenser in way of frame 41 - 42 (port side) being specially examined and dealt with as necessary at the next drydocking. I shall be glad to learn whether these items were in fact dealt with at the time of your survey.

It is concluded that the forced draught fans were examined, but your confirmation is desired.

Yours faithfully,

Pro Clerk to the
Classification Committee.

The Surveyors,
RIO DE JANEIRO.



© 2021

Lloyd's Register
Foundation

011091-011038-0163